# Fall 2012 Levee Maintenance Deficiency Summary Report Overall LMA & Unit Ratings, including USACE Erosion Survey

### Sacramento River Basin

ST0008 Sacramento Maintenance Yard	Overall LMA Rating	Total LMA Miles						
Sacramento Bypass	A	3.51						
Rated Item		Maintena	nce Deficiancy		Enforc	ement	Design & System Obsolescence	
Rateu item	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
Earthen Levee								
Slope Stability	0.01		0.01	0.29%				
LMA Totals:	0.01	0.00	0.01	0.29%	0.00	0.00	0.00	0.00
Unit No. 01 Sacramento Bypass or North Levee RB	Overall Unit Rating	Total Unit Miles						
ST0008	Α	1.73						
Rated Item	Maintenance Deficiancy				Enforcement		Design & System Obsolescence	
Nateu item	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
Earthen Levee								
Slope Stability	0.01		0.01	0.58%				
Unit Totals:	0.01	0.00	0.01	0.58%	0.00	0.00	0.00	0.00
Unit No. 02 Sacramento Bypass or South Levee LB	Overall Unit Rating	Total Unit Miles						
ST0008	Α	1.78						
Rated Item	Maintenance Deficiancy				Enforc	ement		& System scence
Nateu item	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
No Items								
Unit Totals:	0.00	0.00	0.00	0.00%				

## **LMA District Cover Sheet**

## Fall 2012 Levee Inspection Results

# **Sacramento Maintenance Yard Sacramento Bypass**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)						
* Overall LMA Rating (Fall Only)			A							
	** Non-receipt of Su	ımmer or Winter Inspe	ection Reports may effec	et overall annual rating						
* <u>SPRING INSPECTIONS:</u> Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.										
FALL INSPECTIONS: The overall maintena within the attached ur		ve is based on operati	ion and maintenance de	ficiencies identified						
Comments										

## **Unit Cover Sheet**

## Fall 2012 Levee Inspection Results

# **Sacramento Maintenance Yard Sacramento Bypass**

Waterway	Bank	Unit Miles
Unit No. 01 Sacramento Bypass or North Levee	Right	1.73

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	03/23/2012 - 03/23/2012		10/09/2012 - 10/09/2012	
DWR Inspector	John Williamson		John Williamson	
Accompanied By	Casey Lund Sac maint		Casey Lund Sac maint	

#### Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

### http://cdec.water.ca.gov/lma.html

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

# Levee Inspection Report By Mile - Fall 2012

# **Sacramento Maintenance Yard Sacramento Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento Bypass or North Levee	Right	1.73	10/09/2012 10/09/2012	John Williamson

LMR			Rating ** +		Action/Comment	GPS Latitud	Issue No.		
No.	Start	End	Calegory	пеш	tion +	Action/Comment	Start	End	Photo
1	0.38	0.38	Earthen Levee	Encroachments	WS C En		38.605075 ° -121.566400 ° DWR ID: DWR_S	38.605075 ° -121.566400 ° <sup>T0008</sup> _01_s _ 2012	
2	0.46	0.46	Earthen Levee	Slope Stability	LS M Ma		38.604712 ° -121.567738 ° DWR ID: DWR_S	38.604712 ° -121.567738 ° T0008_01_s _ 2012	Υ

\* Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiancy Ob : Design & System Obsolescence En : Enforcement

## Levee Inspection Report By Mile - Fall 2012

# **Sacramento Maintenance Yard Sacramento Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento Bypass or North Levee	Right	1.73	10/09/2012 10/09/2012	John Williamson

Levee Mile Report Line	2							
Start Levee Mile	0.46							
End Levee Mile	0.46							
Location	Land Side							
Category	Earthen Levee							
Item	Slope Stability							
Bulge at the toe of the levee slope. Photo fall 2012.								
johngw_f_20121015_741.jpg								



## **Unit Cover Sheet**

## Fall 2012 Levee Inspection Results

# **Sacramento Maintenance Yard Sacramento Bypass**

Waterway	Bank	Unit Miles
Unit No. 02 Sacramento Bypass or South Levee	Left	1.78

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	03/23/2012 - 03/23/2012		10/09/2012 - 10/09/2012	
DWR Inspector	John Williamson		John Williamson	
Accompanied By	Casey Lund Sac maint		Casey Lund Sac maint	

#### Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

### http://cdec.water.ca.gov/lma.html

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

# Levee Inspection Report By Mile - Fall 2012

# **Sacramento Maintenance Yard Sacramento Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento Bypass or South Levee	Left	1.78	10/09/2012 10/09/2012	John Williamson

LMR	Levee	Mile	Catagami	Itom	- Ration (Comment		Item ** Total ** Tota		Loca	GPS Latitude	e/Longitude	Issue No.
No.	Start	End	Category	item	tion	ing +	Action/Comment	Start	End	Photo		
1			Earthen Levee	Operations & Maintenance Manuals	LS	A Ma		o o DWR ID: DWR_STO	o o 0008_02_s _ 2012_	J		
2			Earthen Levee	Emergency Supplies & Equipment	LS	A Ma		o o DWR ID: DWR_ST(	o 0008_02_s _ 2012_	Ü		
3			Earthen Levee	Flood Preparedness & Training	LS	A Ma		o o DWR ID: DWR_ST(	0008_02_s _ 2012_	ı		
4	0.09	1.07	Earthen Levee	Vegetation	LS	A Ma	V1 : Control annual grass and weeds on the levee slopes and easements. Inspector Comments: Vegetation is taller than 12 inches at the lower 20-25 feet of slope.	38.602360 ° -121.557188 ° -				

N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain + Issue Type

Ma : Maintenance Deficiancy Ob : Design & System Obsolescence En : Enforcement

## Levee Inspection Report By Mile - Fall 2012

# **Sacramento Maintenance Yard Sacramento Bypass**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sacramento Bypass or South Levee	Left	1.78	10/09/2012 10/09/2012	John Williamson

Levee Mile Report Line	4		
Start Levee Mile	0.09		
End Levee Mile	1.07		
Location	Land Side		
Category	Earthen Levee		
Item	Vegetation		
Grasses on the landside toe taller then 12 inches. Photo fall 2012			
johngw_f_20121015_737.jpg			

